

**TOSHIBA**

TOSHIBA POS Terminal

**ST-M30**

# **OPOS Driver Kit Release Notes**

THIRD Edition: Jan 10, 2014

**TOSHIBA TEC CORPORATION**

## **Revision Record**

<b>Rev. No.</b>	<b>Date</b>	<b>Description</b>
V001.000	19 April 2012	First Release
V001.001	18 July 2012	Update TEC Driver, Printer and Keyboard installer with new TECUSB driver
V001.002	10 Jan 2014	Update Drawer OPOS installer with new driver



**Table of Contents**

Supplies..... 1

Folder Configuration ..... 1

Caution ..... 2


## **Supplies**

The ST-M30 OPOS Driver Kit supplies the following items:

- ◆ Native Driver Kit
- ◆ Drawer OPOS Driver Kit
- ◆ Hybrid MCR OPOS Kit
- ◆ Keylock OPOS Kit
- ◆ Line Display OPOS Kit
- ◆ MCRRMS OPOS Kit
- ◆ TEC Keyboard OPOS Kit
- ◆ Printer OPOS Kit

## **Folder Configuration**

The Folder Configuration is as follows:



## **Caution**

**NOTE:** For restoring the divided files, save the following files in the same folder of HDD.

Ex) When a version is V001.xxx

ST-M30OPOSV1xxx.000

ST-M30OPOSV1xxx.001

ST-M30OPOSV1xxx.002

ST-M30OPOSV1xxx.003

.

.

.

ST-M30OPOSV1xxx.bat

Execution of "ST-M30OPOSV1xxx.bat" restores "ST-M30OPOSV1xxx.zip" to the same location as "ST-M30OPOSV1xxx.bat"

**NOTE1:** For WEPOS, the installer might have problem for "Upgrade". Please perform un-installation for older installer and perform installation with newer version of installer.

**NOTE2:** The un-installation might have problem to remove the device driver. If happen, please remove the device driver from Device Manager manually.  
<Start> → <Run> → type "devmgmt.msc" and press "Enter"  
Right clicks the TEC device to be uninstall and select "Uninstall"  
Please make sure that the device will not be use anymore.

**NOTE3:** Make sure system is fresh boot-up (not running any OPOS application) before performing any upgrade installation or un-installation.